



Steps to install Orcad 17.2 Lite


1. Go to the link <http://tinyurl.com/eee1001> (copy and paste this URL link in your web browser and hit "Enter Key")
2. Click on download all (523MB Zipped file size)




3. Unzip this file in a folder




4. Open the ORCAD17.2 LITE folder




5. Inside the ORCAD17.2 LITE folder, the 17.2_OrCAD_Lite_Capture_PSpice to be unzipped.



6. After unzipping 17.2_OrCAD_Lite_Capture_PSpice, it will look like this




7. Right mouse click on the setup.exe file and Run as administrator




8. A popup windows will appear, just click on "Yes"


9. Click on "Next"




10. Accept the License agreement and click "Next".



11. Click on “Next” by selecting recommended settings.




12. Browse to a location where the software to be installed and Click on “Next”.



13. A popup window will appear, in that just Click on “Next”


14. Installation begins.




15. Installation continues




16. Click on "Finish"




17. After successful installation go to "Start Menu" bar and Select "Cadence Release 17.2-2016".



18. Click on “Capture CIS Lite” and wait for few seconds.



19. Without any issues the Orcad Software will open its main page and it looks like this.



20. That's it.... You have successfully installed “Orcad 17.2 Lite” version software in your PC.